

## Product Safety Recall

2014 DBA4418



*\*Note the above image is for reference only – Only batches between June 2013 and May 2014 are affected by this recall.*

### **Recall of 2014 DBA4418**

Disc Brakes Australia Pty Ltd (DBA) has become aware that specific batches of its 4000 series DBA4418 series disc rotors may crack or separate if they experience thermal shock, typically associated with motorsport racing. A vehicle driven under normal conditions is unlikely to experience heat shock or any associated failure of the DBA4418 rotor.

The impacted rotors are identifiable by roll marks on the side of the disc rotor with dates between **June 2013 and May 2014** and are identified by part numbers **DBA4418, DBA4418S (slotted), DBA4418XS (cross drilled and slotted rotors) - (collectively 2014 DBA4418)**. The rotors are designed for fitment on the front axle of selected 4 door Mitsubishi Lancer EVO model vehicles from 1998 to 2007.

Please note this recall is limited to DBA4418 disc rotors with dates between and including **June 2013 and May 2014** and does not impact any other rotor applications or product with dates outside this range.

All DBA brake rotors contain a 'roll mark' on the side of the disc to ensure total traceability (as pictured above).



# Product Safety Recall

## 2014 DBA4418

### How do I know if my vehicle is affected?

The 2014 DBA4418 was designed to fit the front axle of selected 4 door Mitsubishi Lancer EVO model vehicles from 1998 to 2007. The product was able to be fitted to the following vehicles:

- Mitsubishi Lancer EVO V, EVO VI CE (4 door sedan) 1998 – 2001 2.0 litre 4G63T I4 16V DOHC
- Mitsubishi Lancer EVO V, EVO VI CP CT (4 door sedan) 1998 – 2001 2.0 litre 4G63T I4 16V DOHC
- Mitsubishi Lancer EVO VII, EVO VIII CT (4 door sedan) 2001 – 2005 2.0 litre 4G63T I4 16V DOHC
- Mitsubishi Lancer EVO VII, EVO VIII CZ (4 door sedan) 2001 – 2005 2.0 litre 4G63T I4 16V DOHC
- Mitsubishi Lancer EVO IX CT (4 door sedan) 2005 – 2007 2.0 litre 4G63T I4 16V DOHC MIVEC
- Mitsubishi Lancer EVO IX CY (4 door sedan) 2005 – 2007 2.0 litre 4G63T I4 16V DOHC VVT
- Mitsubishi Lancer EVO IX CY (4 door wagon) 2005 – 2007 2.0 litre 4G63T I4 16V DOHC

DBA's last sale of these batches of 2014 DBA4418 product to its distribution network was in August 2014, however product may have existed in supply chains after this date.

### What to do

To check if your product is impacted by DBA's voluntary recall program, please confirm both the **DBA part number** and **date** on the disc rotor's roll mark.

The roll mark is located on the side of the rotor (the front wheels will need to be removed to confirm). We are asking drivers of affected Mitsubishi Lancer models to check their rotors or take their car to a mechanic to have the rotors checked.

An illustration of how to identify has been provided above.

- **DBA Part Number**
  - The DBA Part Number on the roll mark impacted are: **DBA4418HC**
- **Manufacturer date**
  - The manufacturing dates are printed as Day / Month / Year
  - Impacted batches are for between the dates **xx0613** and **xx0514**

### Contact details

If you have a 2014 DBA4418 rotor, the owner of the vehicle or mechanic should contact **Disc Brakes Australia on 1800 730 039, [inquiries@dba.com.au](mailto:inquiries@dba.com.au) or at [www.dba.com.au](http://www.dba.com.au)**. DBA will provide a refund or replacement - plus reasonable labour costs for the inspection and replacement of new rotors.

Disc Brakes Australia sincerely regrets any inconvenience caused and wants to work with anyone with impacted DBA4418 rotors to retrieve the product and will provide a replacement as soon as possible.

Anyone with a 2014 DBA4418 rotor is advised not to participate in any racing activity or track days until a replacement rotor is installed.